




GENERAL NOTE: CAREFULLY REMOVE ALL WRAPPING MATERIALS AND ENSURE ALL PARTS ARE ACCOUNTED FOR. ASSEMBLE ON A CLEAN FLAT SURFACE TO AVOID SCRATCHES. DO NOT DISCARD THE PACKAGING UNTIL ITEM IS FULLY ASSEMBLED.



① x1



② x1



M6x25

Ⓐ x2



M6x16

Ⓑ x2



Ø16

Ⓒ x4



4#

Ⓓ x1

